
JABSCO PUMPS MODEL: 8170-9001



(Model 8170-9001 replaces 8170 and 8170f)

DESIGN FEATURES

Body: Bronze
Impeller: Neoprene
Shaft: Stainless Steel
Bearings: Ball Bearing
Ports: 3/4" I.P.T.

SERVICE KITS

MINOR SERVICE KIT- For "onboard" repairs-includes impeller, seal and gasket.

MAJOR SERVICE KIT- For major pump overhaul includes all parts except body,

APPLICATION: Marine engine cooling for Chrysler marine engines series M·46·4, M·47·4.

King .

Moose 8170-9001

OPERATING INSTRUCTIONS

- 1. INSTALLATION-Care should be taken that the intake and discharge piping of the engine corresponds with the port as shown on the installation drawing.
- 2. DRIVE-Direct.

enmodelinger a relieve six arriver as in the


- 3, SPEEDS-Pump is designed to operate through the entire engine range.
- SELF-PRIMING-Jabsco Pumps will operate satisfactorily at low as well as high speeds. Be sure suction lines are airtight.
- RUNNING DRY- Impeller depends on liquid pumped for lubrication. DO NOT RUN DRY for more than 30 seconds. Lack of liquid will burn the impeller.
- PRESSURES- Excessive back pressure due to scale and rust deposits in the water passages will reduce the flow and cause engine to overheat.
- TEMPERATURES-Impeller specially compounded to operate through the range of 45⁰ .180⁰ F. For temper' atures of 27⁰ '45⁰ F. use .09 impeller.

- 8. FREEZING WEATHER- Drain unit by loosening end cover plate, For closed systems, use one of the fO!lowing\anti-freeze compounds: Atlas "Permaguard", DuPont "Zerex". Dow Chemical "Dowguard". "Pyro", or "Telar". Do not use petroleum based anti-freeze compounds,
- IMPELLER REPLACEMENT- Remove end cover. Withdraw impeller by grasping impeller hub with pliers.
- GASKET REPLACEMENT-Always use standard pump part. A thicker gasket will reduce priming ability. A thinner gasket will cause impeller binding.
- 11. CAM REPLACEMENT- Coat top surface of new cam and cam screw threads with permatex #1 or equivalent sealing compound before installing.
- 12. SPARE PARTS- Avoid costly shut downs by always having a JABSCO Service Kit on hand.



www.PumpAgents.com

EXPLODED VIEW



Patented and Patents Pending

PARTS LIST

KEY	PART NO.	OTY, REO'C.	DESCRIPTION
I	91003.0010	6	End Cover Screw
2	I 1831 -00000	I	End Cover
3	3101 .0000	1	' Gasket
	920-0001	1	*Impeller
S	4156.0000	7	Wearplate
6	96080.0080	"	'Seal
7	91004.0110	,	Cam Screw
8	3255-0000	1	Cam
9	8174.9000	I	BodV
' 0	8177-0410	,	Shaft
11	91402.0060	"	Key
'2	913-0000	,	Bearing Seal
' 3	92600-0060	,	Ball Bearing
, .	91701 · 1850	7	Retaining Ring
'S	8176.0000	7	Coupling
'6	91700-2470	Ţ	Retaining Ring


90118-0001 Service Kit contains parts marked with aner.sk.


Model 8170 Up Seal Version (obsolete)

92700-0060 . Seat 92000-0210· '0' Ring 3166 - Spacer 3298 - Slinger

Face seal cannot be installed in lip seal version.

INSTALLATION DRAWING





JABSCO PRODUCTS IIII

Marine and Recreation Components Division Inlernational Telephone and Telegraph Corporation 1485 Dale Way, Costa Mesa, Celilornia 92626

Telephone: (714) 545-8251